


600 VA Toroid transformer with Rectif. and 100000 myF Capacitor direct switch on



16 A B-line protector trips because of Inrush